


Spare part list Z-10
#0200-000-01
07-11-2007



Qty	Item No.	Part Number	Description
1	1	01.004.02	Zoom housing
1	2	01.008.01	Zoom knob
1	3	01.025.01	Cable protector
1	4	01.020.02	Zoom drive plate
1	5	01.006.02	Head
1	6	01.016.01	Toothed ring
1	7	01.007.02	Clamping block
1	8	01.017.01	Draw bolt
1	9	01.001.02	Frame
1	10	01.002.01	Cover left
1	11	01.003.01	Cover right
2	12	01.080.01	Gasket (2x400MM.)
1	13	01.021.02	Zoom catch plate
1	14	01.022.01	Pin 5h6X40 ISO8734 st
1	15	01.023.01	Zoom shaft bush
1	16	01.019.02	Zoom pot holder
1	17	01.031.01	Zoom spring pin
1	18	01.024.01	Zoom latch
1	19	01.030.02	Zoom latch pin
1	20	01.029.01	Mode switch bush
1	21	01.027.01	Set print spacer
1	22	01.026.01	Window
1	23	01.254.01	Mounted circuit board "display"
4	24	01.033.02	Rubber bush
1	25	01.032.02	Zoom speed bush
1	26	01.034.02	Return switch extender
1	27	01.252.01	Mounted circuit board "Ret button"
1	28	01.251.01	Mounted circuit board "EZ/VTR button"
1	29	01.028.02	EZ print spacer
1	30	01.018.02	Connector plate
1	31	01.255.01	Zoom potentiometer
4	32	01.035.01	Rubber switch cap
1	33	01.263.01	Switch ckspdth
2	34	01.039.01	Screw M5X16 DIN7984 A2 70
2	35	01.044.01	Pin 2h6X16 ISO8734 st
1	36	01.052.01	Ring DIN125 A2,2 140V Zn
1	37	01.050.01	Screw M2x12 DIN912 12.9 A2A
4	38	01.046.01	Pin 3h6X10 ISO8734 st
2	39	01.078.01	Ring borgri-5.3-st-zn
6	40	01.047.01	Screw M2X5 DIN7985 4,8 ZNZ
4	41	01.041.01	Screw M2,5X4 DIN916 45H A2A
10	42	01.051.01	Screw M2x8 DIN 912 A2 70
1	43	01.043.01	Pin 2X10 ISO8752 RVS A1
6	44	01.042.01	Pin 2,5m6X18 ISO8734 st.
4	45	01.057.01	Nut M2 DIN934 A2 70
2	46	01.058.01	Screw M1,6X4 DIN965 A2 70
6	47	01.079.01	Ring borgri-2.7-st-zn
2	48	01.049.01	Screw M3X8 DIN912 A2 70
3	49	01.040.01	Screw M4X45 DIN912 A4 70
2	50	01.053.01	Screw M2X4 DIN965 A2 70
3	51	01.085.01	Ring borgri-4.3-st-zn
8	52	01.038.01	Screw M2,5X8 DIN912 A2 70
3	53	01.086.01	Ring 2,2X5 DIN125-POL.6.6
1	54	01.037.01	Zoom latch spring
2	55	01.036.01	Ball bearing MF85ZZS
1	56	01.257.01	connector 12p CH HRS
1	57	01.256.01	Potential meter zoom speed
1	58	01.264.01	Mounted circuit board "Main board Z-1
1	59	01.076.01	Focus shaft Z-10
1	60	01.059.01	Focus knob Z-10